

MAZDA B1014: RAIN SENSOR/AUTO LIGHT SENSOR MALFUNCTION

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$100-\$250
Can I Still Drive?	:	Yes (Short-term only)

What Does The Mazda B1014 Code Mean?

Auto light/wiper control module detects rain sensor/auto light sensor internal malfunction.

What Are The Potential Causes Of The Mazda B1014 Code?

- Rain sensor/auto light sensor malfunction
- Auto light/wiper control module malfunction

Reference Sources

[Mazda B1014](#), DTCDECODE.