

MAZDA B2869: WHEEL UNIT NO.2 INTERNAL MALFUNCTION

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$50-\$500
Can I Still Drive?	:	Yes

What Does The Mazda B2869 Code Mean?

The instrument cluster receives error signals from the wheel unit.

What Are The Potential Causes Of The Mazda B2869 Code?

Internal malfunction of wheel unit

Reference Sources

[Mazda B2869](#), DTCDECODE.