

MERCEDES-BENZ P1225: RESONANCE INTAKE MANIFOLD SWITCHOVER VALVE

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$150-\$700
Can I Still Drive?	:	No

What Are The Potential Causes Of The Mercedes-Benz P1225 Code?

Wiring/connectors

Reference Sources

[Mercedes-Benz P1225](#), DTCDECODE.