

MERCEDES-BENZ P1542: PEDAL VALUE SENSOR

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$100-\$300
Can I Still Drive?	:	Yes (Short-term only)

What Are The Potential Causes Of The Mercedes-Benz P1542 Code?

Wiring/connector

Reference Sources

[Mercedes-Benz P1542](#), DTCDECODE.