

MERCEDES-BENZ P1550: A/C COMPRESSOR TORQUE IMPLAUSIBLE

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$200-\$1500
Can I Still Drive?	:	Yes

What Does The Mercedes-Benz P1550 Code Mean?

Read out fault memory of control unit AAC. If fault code [P1491](#), P1550 is present, the fault is detected by the AAC control and operating unit and appropriate message is transmitted through the interior CAN to the ME-SFI control unit.

Reference Sources

[Mercedes-Benz P1550](#), DTCDECODE.