

MINI P1741: CLUTCH SOLENOID CIRCUIT OPEN CIRCUIT

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$100-\$300
Can I Still Drive?	:	Yes

What Does The MINI P1741 Code Mean?

The clutch solenoid circuit continuity is in error. This test is performed by the GIB (Gearbox Interface Box), a system dedicated to low level control of the transmission control unit.

What Are The Potential Causes Of The MINI P1741 Code?

- Short to battery
- Short to ground
- Open circuit

Reference Sources

[MINI P1741](#), DTCDECODE.