

NISSAN C1310: ABS HV SYSTEM

OVERVIEW

Severity	:	<div></div> High
DIY Difficulty Level	:	<div></div> Advanced
Repair Cost	:	\$900-\$1100
Can I Still Drive?	:	No

What Does The Nissan C1310 Code Mean?

The traction control prohibition signal is received for at least 0.07 seconds when IG1 terminal voltage is 10.5 V or more for at least 1.5 seconds and communication with HV ECU is valid.

What Are The Potential Causes Of The Nissan C1310 Code?

Hybrid control system

Reference Sources

[BRAKE CONTROL SYSTEM SERVICE MANUAL for C1310](#) - Page 108.