

## RAM B1A8F: IGNM PHOTO POSITION FAILURE

### OVERVIEW

Severity	:	<div></div> High
DIY Difficulty Level	:	<div></div> Advanced
Repair Cost	:	\$50-\$250
Can I Still Drive?	:	No

### What Does The RAM B1A8F Code Mean?

The Radio Frequency Hub (RF-Hub) detects an internal fault in the Ignition Node Module (IGNM).

### What Are The Potential Causes Of The RAM B1A8F Code?

- Ignition node module (IGNM)
- Radio frequency hub module (RF hub)

### Reference Sources

[Accessories And Equipment Radio Frequency \(RF Hub\) Module Electrical Diagnostics for B1A8F](#) - 2014 RAM 3500 HD Laramie, pages 147-148.