

SAAB P1572: IMM CIRCUIT FAILURE (EXCEPT ANTENNA CIRCUIT)

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$150-4350
Can I Still Drive?	:	Yes

What Does The Saab P1572 Code Mean?

When starting the engine. Communication failure between body integrated unit and Control module. Incorrect immobilizer key (Use of unregistered key in body integrated unit.

What Are The Potential Causes Of The Saab P1572 Code?

- Poor connections
- Wrong key
- Faulty body integrated unit
- Faulty Control module

Reference Sources

[Technical Service Bulletin PIP5094 for P1572](#)