

SUBARU P1448: FUEL TANK SENSOR CONTROL VALVE RANGE/PERFORMANCE

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$200-\$300
Can I Still Drive?	:	Yes (Short-term only)

What Does The Subaru P1448 Code Mean?

Engine started, vehicle driven at cruise speed and then back to idle, and the PCM detected a problem in the operation of the Atmospheric Pressure valve system during the CCM test period.

What Are The Potential Causes Of The Subaru P1448 Code?

- Check for other DTC on display
- Check fuel filler cap
- Check evaporative emission line

Reference Sources

[Subaru P1448](#), DTCDECODE.