

SUBARU P1560: BACK-UP VOLTAGE CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes (Short-term only)

What Does The Subaru P1560 Code Mean?

Battery voltage \geq 10.9 V. Engine condition – After engine starting. Low voltage condition of back-up power supply.

What Are The Potential Causes Of The Subaru P1560 Code?

- Wiring harness between ECM and ground chassis needs repair.
- Poor contact of the ECM connector.
- Defective fuse.
- Wiring harness between ECM and negative battery terminal needs repair.

Reference Sources

[Testing and Inspection for P1560](#) - 2004 FORESTER SERVICE MANUAL, pages 215-216.