

## SUBARU P1572: IMM CIRCUIT FAILURE (EXCEPT ANTENNA CIRCUIT)

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$150-4350
Can I Still Drive?	:	<b>Yes</b> (Short-term only)

### What Does The Subaru P1572 Code Mean?

Communication failure between body integrated unit and ECM.

### What Are The Potential Causes Of The Subaru P1572 Code?

- Open or short circuit between body integrated unit and fuse
- Open or short circuit between the body integrated unit and ignition switch
- Open circuit of the body integrated unit ground circuit
- Faulty ECM ground circuit
- Open circuit of the harness between the body integrated unit and ECM
- Faulty body integrated unit
- Faulty ECM

### Reference Sources

[Diagnostic Trouble Code \(DTC\) Detecting Criteria for P1572](#) - Page 192