SUBARU P1577: IMM CONTROL MODULE EEPROM		
		OVERVIEW
Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$300-\$600
Can I Still Drive?	:	Yes (Short-term only)

What Does The Subaru P1577 Code Mean?

Body integrated unit malfunctioning, failed to access the ROM inside the body integrated unit.

What Are The Potential Causes Of The Subaru P1577 Code?

- Perform registration to all keys used for the vehicle
- Faulty body integrated unit

Reference Sources

<u>Diagnostic Trouble Code (DTC) Detecting Criteria for P1577</u> - Page 192

