SUBARU P1596: AUTOMATIC TRANSAXLE DIAGNOSIS **INPUT SIGNAL CIRCUIT HIGH INPUT OVERVIEW**

Severity

DIY Difficulty Level

Repair Cost \$75-\$200

Can I Still Drive? Yes (Short-term only)

What Does The Subaru P1596 Code Mean?

Key on or engine running; and the PCM detected an unexpected "high" voltage condition on the A/T Diagnosis Signal circuit (5-volt) during the CCM test.

What Are The Potential Causes Of The Subaru P1596 Code?

- Check harness between ECM and TCM connector
- Check output signal for ECM
- Check poor contact
- Check harness between ECM and TCM connector

Reference Sources

2001 FORESTER SERVICE MANUAL FOR P1596 - Pages 337-338.

