

## SUBARU P1701: CRUISE CONTROL SET SIGNAL CIRCUIT MALFUNCTION FOR AUTOMATIC TRANSMISSION

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$150-\$250
Can I Still Drive?	:	<b>Yes</b> (Short-term only)

### What Does The Subaru P1701 Code Mean?

Engine started, vehicle driven to a speed over 30 mph, and the PCM detected an unexpected voltage condition on the data line between the Cruise Control Module (CCM) and the PCM.

### What Are The Potential Causes Of The Subaru P1701 Code?

- Check harness between TCM and CCM
- Check input signal for TCM

### Reference Sources

[Diagnostics Chart with Trouble Codes for P1701](#) - Pages 240-242.