SUBARU U1201: CAN-HS COUNTER ABNORMAL			
		OVERVIEW	
Severity	:		High
DIY Difficulty Level	:		Advanced
Repair Cost	:	\$550-\$750	
Can I Still Drive?	:	No	

What Does The Subaru U1201 Code Mean?

High speed CAN communication becomes unstable.

What Are The Potential Causes Of The Subaru U1201 Code?

- Bad wiring harness
- Open or short circuit
- Poor connector terminal on the ECM
- Defective yaw rate sensor
- Defective ECM

Reference Sources

<u>Diagnostic Procedure with Diagnostic Trouble Code for U1201</u> - 2008 Impreza WRX, pages 45-47.

