

SUBARU U1221: CAN-HS ECM NO-RECEIVE DATA

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes (Short-term only)

What Does The Subaru U1221 Code Mean?

Not received error data from ECM.

What Are The Potential Causes Of The Subaru U1221 Code?

- Wiring harness used by CAN communication line needs repair.
- Defective ECM.

Reference Sources

[Diagnostic Procedure with Diagnostic Trouble Code for U1221](#) - 2008 Impreza WRX, pages 57-58.