

SUBARU U1300: CAN-LS MALFUNCTION

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes (Short-term only)

What Does The Subaru U1300 Code Mean?

Either end of low-speed CAN communication line is open or shorted, the connector is not connected properly, or the terminal has poor crimping.

What Are The Potential Causes Of The Subaru U1300 Code?

- Wiring harness used by CAN communication lines need repair.
- Navigation or audio unit needs repair.
- Auto A/C control module needs repair.
- Body integrated unit needs repair.
- Defective combination meter.

Reference Sources

[Diagnostic Procedure with Diagnostic Trouble Code for U1300](#) - 2008 Impreza WRX, pages 63-64.