

SUBARU U1301: CAN-LS COUNTER ABNORMAL

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The Subaru U1301 Code Mean?

Communication becomes unstable because of low speed CAN communication error. Display error may occur in fuel gauge because the CAN communication is not transmitted (sending/receiving) normally.

What Are The Potential Causes Of The Subaru U1301 Code?

- Wiring harness used by CAN communication lines need repair
- Navigation or audio unit needs repair
- Auto A/C control module needs repair
- Body integrated unit needs repair
- Defective combination meter

Reference Sources

[Diagnostic Procedure with Diagnostic Trouble Code for U1301](#) - 2008 Impreza WRX, pages 65-67.