

## SUBARU U1321: CAN-LS METER NO-RECEIVE DATA

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

### What Does The Subaru U1321 Code Mean?

Not received error data from combination meter. Engine may not be started. DTC [U1301](#) or [U1302](#) not displayed.

### What Are The Potential Causes Of The Subaru U1321 Code?

- Defective combination meter
- Wiring harness connected to low speed CAN communication lines need repair
- Defective body integrated unit
- Poor contact of wiring harness used for low speed CAN communication line

### Reference Sources

[Diagnostic Procedure with Diagnostic Trouble Code for U1321](#) - 2008 Impreza WRX, pages 71-72.