TOYOTA B15A8: TELEMATICS TRANSCEIVER MALFUNCTION

OVERVIEW

Severity : Medium

DIY Difficulty Level : Intermediate

Repair Cost : \$30-\$200

Can I Still Drive? : Yes (Short-term only)

What Does The Toyota B15A8 Code Mean?

Error in EEPROM or PLL IC is detected.

What Are The Potential Causes Of The Toyota B15A8 Code?

DCM (Telematics Transceiver)

Reference Sources

Toyota B15A8, DTCDECODE.

