TOYOTA B15BA: XM TUNER MALFUNCTION		
	OVERVIEW	
:	Medium	
:	Intermediate	
:	\$300-\$500	
:	Yes	
	:	

What Does The Toyota B15BA Code Mean?

When either condition below is met: Internal IC malfunction Stereo component tuner assembly malfunction

What Are The Potential Causes Of The Toyota B15BA Code?

Stereo component tuner assembly

Reference Sources

Toyota B15BA, DTCDECODE.

