

TOYOTA P1010: OCV FOR VVTL CIRCUIT (BANK 1)

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$100-\$200
Can I Still Drive?	:	Yes (Short-term only)

What Does The Toyota P1010 Code Mean?

Open or short in oil control valve for VVTL circuit

What Are The Potential Causes Of The Toyota P1010 Code?

- Open or short in OCV circuit
- OCV for VVT-L
- Oil pressure switch for VVT-L
- ECM

Reference Sources

[Toyota P1010](#), DTCDECODE.