TOYOTA P1011: OCV FOR VVTL OPEN MALFUNCTION (BANK 1)		
		OVERVIEW
Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$100-\$200
Can I Still Drive?	:	Yes

What Does The Toyota P1011 Code Mean?

In the condition that the engine speed is 6,000 rpm or less and the oil pressure switch on for 5 sec. or more.

What Are The Potential Causes Of The Toyota P1011 Code?

- Open or short in OCV circuit
- OCV for VVT-L
- Oil pressure switch for VVT-L
- ECM

Reference Sources

Toyota P1011, DTCDECODE.

