

TOYOTA P3060: BATTERY TEMPERATURE SENSOR CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$100-\$200
Can I Still Drive?	:	Yes

What Does The Toyota P3060 Code Mean?

Open or short in battery temperature sensor circuit
Battery temperature sensor circuit range/performance problem

What Are The Potential Causes Of The Toyota P3060 Code?

- Battery temperature sensor
- Connector and wire harness

Reference Sources

[Prius Repair Manual for P3060](#) - Page 300.