

VOLKSWAGEN P1386: INTERNAL CONTROL MODULE, KNOCK CONTROL CIRCUIT ERROR

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$800-\$1500
Can I Still Drive?	:	No

What Does The Volkswagen P1386 Code Mean?

Engine started, and the ECM detected a too high or too low voltage condition on the knock control circuits, or a miscommunication between the knock control and the ECM.

What Are The Potential Causes Of The Volkswagen P1386 Code?

ECM has failed

Reference Sources

[Volkswagen P1386](#), DTCDECODE.