

VOLKSWAGEN P1682: POWERTRAIN DATA BUS IMPLAUSIBLE MESSAGE FROM ABS CONTROL MODULE

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$75-\$150
Can I Still Drive?	:	Yes (Short-term only)

What Does The Volkswagen P1682 Code Mean?

Ignition off, the ECU detected a I fault of the ABS control module. The Engine Control Module (ECM) communicates with all databus-capable control modules via a CAN databus.

What Are The Potential Causes Of The Volkswagen P1682 Code?

- Ground between engine and chassis may be broken
- Faulty voltage supply
- ECM has failed

Reference Sources

[Volkswagen P1682](#), DTCDECODE.