4 ELECTRICAL		
OVERVIEW		
everity	:	Medium
Y Difficulty Level	:	Intermediate
epair Cost	:	\$150-\$350
•		

## What Does The Volkswagen P1828 Code Mean?

Engine started, vehicle driven with the solenoid applied, and the ECM detected an unexpected voltage condition on the SS1/C solenoid circuit was incorrect during the test.

## What Are The Potential Causes Of The Volkswagen P1828 Code?

- Solenoid valves in valve body are faulty
- Solenoid circuit is shorting to ground
- Solenoid circuit is open
- TCM has failed or wiring is shorting
- Check harness connector for contact corrosion or water damage
- Check resistance of solenoid valve

## **Reference Sources**

Volkswagen P1828, DTCDECODE.

