

## VOLKSWAGEN P1912: BRAKE BOOSTER PRESSURE SENSOR SHORT CIRCUIT TO B+

### OVERVIEW

|                      |   |                                    |
|----------------------|---|------------------------------------|
| Severity             | : | <div><div>High</div></div>         |
| DIY Difficulty Level | : | <div><div>Intermediate</div></div> |
| Repair Cost          | : | \$200-\$300                        |
| Can I Still Drive?   | : | <b>Yes</b> (Short-term only)       |

### What Does The Volkswagen P1912 Code Mean?

Key on or engine running, the ECM detected an error with the brake booster pressure sensor signal.

### What Are The Potential Causes Of The Volkswagen P1912 Code?

- Circuit short to ground or open
- Brake booster pressure sensor has failed or is dirty
- ECM has failed

### Reference Sources

[Volkswagen P1912](#), DTCDECODE.