

What Does The Volkswagen P1912 Code Mean?

Key on or engine running, the ECM detected an error with the brake booster pressure sensor signal.

What Are The Potential Causes Of The Volkswagen P1912 Code?

- Circuit short to ground or open
- Brake booster pressure sensor has failed or is dirty
- ECM has failed

Reference Sources

Volkswagen P1912, DTCDECODE.

