

VOLKSWAGEN P3047: ACTIVATION STARTER RELAY 2 SHORT CIRCUIT TO B+

OVERVIEW

Severity	:	<div><div>High</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$50-\$150
Can I Still Drive?	:	No

What Does The Volkswagen P3047 Code Mean?

ECT at start, 10-40° C Engine speed sensor line "KL50R"

Reference Sources

[Volkswagen P3047](#), DTCDECODE.