

VOLKSWAGEN P308D: FUEL PUMP SPEED LOW

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Advanced</div></div>
Repair Cost	:	\$50-\$600
Can I Still Drive?	:	Yes (Short-term only)

What Does The Volkswagen P308D Code Mean?

Phase current > 35 A or Speed deviation > 10%. Ignition ON 1.1 or 5 Sec.

What Are The Potential Causes Of The Volkswagen P308D Code?

Fuel pump module or circuit

Reference Sources

[Volkswagen P308D](#), DTCDECODE.