

ACURA B1136: RIGHT REAR POWER WINDOW SWITCH INTERNAL ERROR

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Advanced</div></div>
Repair Cost	:	\$200-\$550
Can I Still Drive?	:	Yes (Short-term only)

What Does The Acura B1136 Code Mean?

This code indicates inoperative or intermittent operation of the right rear power window.

Note: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

What Are The Potential Causes Of The Acura B1136 Code?

Below are some possible causes of this DTC:

- Loose or poor connections
- Faulty right rear power window switch

Reference Sources

[Acura B1136](#), DTCDECODE.