

ACURA B1147: LEFT REAR POWER WINDOW POSITION INFORMATION ERROR

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Advanced</div></div>
Repair Cost	:	\$80-\$150
Can I Still Drive?	:	Yes

What Does The Acura B1147 Code Mean?

Faulty left rear power window motor operation.

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

What Are The Potential Causes Of The Acura B1147 Code?

- Power window control unit needs to be reset
- Faulty left rear power window motor

Reference Sources

[Acura B1147](#), DTCDECODE.