

ACURA B1149: RIGHT REAR POWER WINDOW POSITION INFORMATION ERROR

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$80-\$150
Can I Still Drive?	:	Yes (Short-term only)

What Does The Acura B1149 Code Mean?

This code indicates faulty operation of the right rear power window motor.

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

What Are The Potential Causes Of The Acura B1149 Code?

Below are some possible causes of this DTC:

- Power window control unit needs to be reset
- Faulty right rear power window motor

Reference Sources

[Acura B1149](#), DTCDECODE.