ACURA B1149: RIGHT REAR POWER WINDOW POSITION INFORMATION ERROR OVERVIEW Severity : Medium DIY Difficulty Level : Advanced Repair Cost : \$80-\$150

Yes (Short-term only)

What Does The Acura B1149 Code Mean?

Can I Still Drive?

This code indicates faulty operation of the right rear power window motor.

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

What Are The Potential Causes Of The Acura B1149 Code?

Below are some possible causes of this DTC:

- Power window control unit needs to be reset
- Faulty right rear power window motor

Reference Sources

Acura B1149, DTCDECODE.

