

ACURA B1382: POWER TAILGATE CLOSER UNIT FULL LATCH SWITCH CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

What Does The Acura B1382 Code Mean?

Poor communication between the Power Tailgate Control Unit and the Power Tailgate Closer Unit.

What Are The Potential Causes Of The Acura B1382 Code?

- Loose or poor connections between the Power Tailgate Control Unit and the Power Tailgate Closer Unit
- "Open" or "Short" between the Power Tailgate Control Unit and the Power Tailgate Closer Unit
- Faulty full latch switch, replace the Power Tailgate Closer Unit
- Power Tailgate Control Unit

Reference Sources

[POWER TAILGATE TROUBLESHOOTING for B1382](#) - Pages 30-38.