

## ACURA B1384: POWER TAILGATE CLOSER UNIT HALF LATCH SWITCH CIRCUIT MALFUNCTION

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes

### What Does The Acura B1384 Code Mean?

Poor communication between the Power Tailgate Control Unit and the Tailgate Closer Unit.

### What Are The Potential Causes Of The Acura B1384 Code?

- Loose or poor connections between the Power Tailgate Control Unit and the Tailgate Closer Unit
- "Open" or "Short" between the Power Tailgate Control Unit and the Tailgate Closer Unit
- Faulty half latch switch, replace the Power Tailgate Closer Unit
- Faulty Power Tailgate Control Unit

### Reference Sources

[POWER TAILGATE TROUBLESHOOTING for B1384](#) - Pages 51-58.