

ACURA B1387: POWER TAILGATE SENSOR PULSE B CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$200
Can I Still Drive?	:	Yes (Short-term only)

What Does The Acura B1387 Code Mean?

This code indicates poor communication between the Power Tailgate Control Unit and the Drive Unit.

NOTE: If the motor does not operate, do the power tailgate motor test.

What Are The Potential Causes Of The Acura B1387 Code?

Below are some possible causes of this DTC:

- Loose or poor connections between the Power Tailgate Control Unit and the Drive Unit
- "Open" or "Short" between the Power Tailgate Control Unit and the Drive Unit
- Faulty power tailgate sensor B, replace the drive unit
- Faulty Power Tailgate Control Unit

Reference Sources

[POWER TAILGATE TROUBLESHOOTING for B1387](#) - Pages 71-77.