

What Does The Acura B2184 Code Mean?

This code indicates Right Power Mirror malfunction (Horizontal).

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

What Are The Potential Causes Of The Acura B2184 Code?

Below are some potential causes of this DTC:

- Check for loose or poor connections
- "Open" or "Short" condition between the Right Power Mirror and the Front Passenger's MPCS unit
- Faulty Right Power Mirror
- Faulty Front Passenger's MPCS unit

Reference Sources

Acura B2184, DTCDECODE.

