## ACURA B2190: FRONT PASSENGER'S POWER WINDOW POSITION DETECT CIRCUIT ERROR OVERVIEW Severity : Medium DIY Difficulty Level : Advanced Repair Cost : \$80-\$150 Can I Still Drive? :: Yes (Short-term only)

## What Does The Acura B2190 Code Mean?

This code indicates Front Passenger's Power Window malfunction.

**NOTE:** If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

## What Are The Potential Causes Of The Acura B2190 Code?

Below are some potential causes of this DTC:

- Faulty Front Passenger's Window Motor
- Faulty Front Passenger's MPCS unit

## **Reference Sources**

Acura B2190, DTCDECODE.

