

ACURA B2190: FRONT PASSENGER'S POWER WINDOW POSITION DETECT CIRCUIT ERROR

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$80-\$150
Can I Still Drive?	:	Yes (Short-term only)

What Does The Acura B2190 Code Mean?

This code indicates Front Passenger's Power Window malfunction.

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

What Are The Potential Causes Of The Acura B2190 Code?

Below are some potential causes of this DTC:

- Faulty Front Passenger's Window Motor
- Faulty Front Passenger's MPCS unit

Reference Sources

[Acura B2190](#), DTCDECODE.