

ACURA B2983: PROBLEM IN THE RECIRCULATION CONTROL LINKAGE, DOOR, OR MOTOR CIRCUIT

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$250-\$350
Can I Still Drive?	:	Yes

What Does The Acura B2983 Code Mean?

Air Recirculation control malfunction.

NOTE: Do the self-diagnostic function with the HDS or climate control unit.

What Are The Potential Causes Of The Acura B2983 Code?

- Loose wires or poor connections on the recirculation control motor circuit
- Faulty Recirculation control motor, control linkage or door
- "Open" or "Short" in the wire(s) between the climate control unit and the recirculation control motor
- Faulty Climate Control Unit

Reference Sources

[2007-2009 Acura MDX HVAC Climate Control Service Manual for B2983](#) - Pages 119-121.