# ACURA P1519: IDLE AIR CONTROL VALVE CIRCUIT MALFUNCTION OVERVIEW Severity : Medium DIY Difficulty Level : Advanced Repair Cost : \$120-\$500 Can I Still Drive? : Yes (Short-term only)

# What Does The Acura P1519 Code Mean?

This code indicates the condition that key on or engine running; and the PCM detected an unexpected voltage condition on the Idle Air Control (IAC) valve control circuit.

### What Are The Potential Causes Of The Acura P1519 Code?

Below are some potential causes of this DTC:

- IAC valve circuit is open, shorted to ground or to system power
- IAC valve power circuit is open or shorted to ground
- IAC valve is damaged or has failed
- PCM is damaged

## **How Can You Fix The Acura P1519 Code?**

TSB 03-006 (3/17/03) contains a repair procedure for this code

# **Reference Sources**

2001 Engine Performance Acura Self-Diagnostics, MDX, 3.2CL & 3.2TL, page 54.

