

## ACURA P1850: A/T BRAKE BAND APPLY SOLENOID CIRCUIT MALFUNCTION

### OVERVIEW

|                      |   |                                    |
|----------------------|---|------------------------------------|
| Severity             | : | <div><div>Medium</div></div>       |
| DIY Difficulty Level | : | <div><div>Intermediate</div></div> |
| Repair Cost          | : | \$200-\$500                        |
| Can I Still Drive?   | : | Yes                                |

### What Does The Acura P1850 Code Mean?

Engine started, then with A/T Brake Band Apply solenoid commanded "on", and PCM detected the solenoid control signal was 12v, or with A/T Brake Band Apply solenoid commanded "off", the solenoid control signal was 1.34 to 1.56 seconds.

Note: This PCN cont

### What Are The Potential Causes Of The Acura P1850 Code?

- A/T Brake band solenoid circuit is open or shorted to ground
- A/T Brake band solenoid High circuit open or shorted to ground
- A/T brake band apply solenoid is damaged or has failed
- PCM has failed

### Reference Sources

[Acura P1850](#), DTCDECODE.