

BMW P1738: PRESSURE CONTROL VALVE 3 ELECTRICAL

OVERVIEW

Severity	:		High
DIY Difficulty Level	:		Intermediate
Repair Cost	:	\$75-\$450	
Can I Still Drive?	:	Yes	

What Does The BMW P1738 Code Mean?

The pressure control valve is not receiving nor sending a signal.

What Are The Potential Causes Of The BMW P1738 Code?

- Pressure control solenoid circuit is shorting to ground
- Pressure control solenoid circuit is open
- Valve has failed
- TCM has failed

Reference Sources

[BMW P1738](#), DTCDECODE.