

## CHRYSLER B106B: REAR DEFROST CONTROL CIRCUIT LOW

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$250-\$350
Can I Still Drive?	:	Yes

### What Does The Chrysler B106B Code Mean?

With the ignition on. Battery voltage greater than 10.4 volts. A shorted low condition on the (C515) Rear Defogger Control Output or (C16) Fused Rear Defogger Control Output circuit

### What Are The Potential Causes Of The Chrysler B106B Code?

- (C515) Rear Window Defogger Control Output Circuit shorted to ground
- (C16) Fused Rear Window Defogger Control Output Circuit partial short to ground (if equipped with heated mirrors)
- Heated Mirrors (if equipped)
- TIPM

### Reference Sources

[Chrysler B106B](#), DTCDECODE.