

CHRYSLER B114C: LEFT REAR HEATED SEAT SWITCH STUCK

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$50-\$350
Can I Still Drive?	:	Yes

What Does The Chrysler B114C Code Mean?

When the Left Rear Heated Seat Switch is held in the on position for over 10 seconds, this code will set.

What Are The Potential Causes Of The Chrysler B114C Code?

- Left Rear Heated Seat Switch Signal Circuit Faulty Wiring
- Ground Circuit Faulty Wiring
- Left Rear Heated Seat Switch
- Left Rear Door Module (DMRL)

Reference Sources

[Chrysler B114C](#), DTCDECODE.