

CHRYSLER B143E: MICROPHONE 2 CIRCUIT LOW

OVERVIEW

Severity	:	Low
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$50-\$100
Can I Still Drive?	:	Yes

What Does The Chrysler B143E Code Mean?

The Hands Free Module detects a fault in any of the microphone circuits.

What Are The Potential Causes Of The Chrysler B143E Code?

- (X722) MICROPHONE 2 IN (+) CIRCUIT SHORTED TO GROUND
- INSIDE REARVIEW MIRROR
- HANDS FREE MODULE

Reference Sources

[Chrysler B143E](#), DTCDECODE.