

What Does The Chrysler B146E Code Mean?

The amplifier detects that the output circuits are shorted together.

What Are The Potential Causes Of The Chrysler B146E Code?

- (X201) AMPLIFIED LEFT FRONT SPEAKER (+) CIRCUIT SHORTED TO THE (X291) AMPLIFIED LEFT FRONT SPEAKER (-) CIRCUIT
- AMPLIFIED LEFT FRONT SPEAKER
- AMPLIFIER

Reference Sources

Chrysler B146E, DTCDECODE.

